

autoDNA

Raport Historii Pojazdu autoDNA

Raport zawiera dostępne informacje na dzień: 2024-11-15 13:28:47 UTC +0100

Wersja językowa: PL

f8e1d41b-4f57274a-8ba1d6c6-8aa8ffda-b9db04a7



Renault Master
VF1VB000260697789

Wiek pojazdu

Wg daty produkcji / roku modelowego

6

LAT(A)

10

MIES.

Data produkcji / Rok modelowy 2018

Wg pierwszej rejestracji pojazdu

6

LAT(A)

1

MIES.

Data pierwszej rejestracji 2018-10-04

9 2 0 0 2 km

Uwaga: Nie jest to aktualny przebieg sprawdzanego pojazdu. System autoDNA oblicza średni przebieg pojazdu na podstawie danych pojazdów o podobnej charakterystyce: marce, modelu, typie paliwa, wieku itp.

CENTRUM POWIADOMIEŃ

Bazy Skradzionych Pojazdów



Przeszukane bazy 11/11

Akcje serwisowe



Nie odnotowano

Informacje o pojeździe



Liczba wpisów 11

Dziennik użytkowania



Liczba wpisów 9

Historia cenowa



Nie odnotowano

Odczyty drogomierza



Liczba wpisów 22

Historia uszkodzeń

 Liczba wpisów 3

Rejestr zastawów

kraj Polska

 Nie odnotowano

Wypożyczenie

 Liczba wpisów 219

Archiwalne zdjęcia

 Liczba wpisów 0

Poprawność VIN

 Niedostępne

INFORMACJE O POJEŹDZIE

Model MASTER	Typ paliwa DIESEL	Pojemność silnika [cm3] 2300
Kolor lakieru YELLOW	Data produkcji 2018	Norma emisji spalin EURO 6B
Moc silnika 96KW (130HP)	Układ kierowniczy LEWOSTRONNY	Typ skrzyni biegów MANUALNA
Napęd FWD	Liczba biegów 6	

AKCJE SERWISOWE

 Nie odnotowano

BAZA SKRADZIONYCH POJAZDÓW

Przeszukane bazy 11

Odnutowano 0

 **Włochy**

Ewidencja pojazdów skradzionych - Policja

 Nie odnotowano

 **Czechy**

Ewidencja pojazdów skradzionych - Policja

 Nie odnotowano

 **Rumunia**

Ewidencja pojazdów skradzionych - Policja

 Nie odnotowano


 **Litwa**

Ewidencja pojazdów skradzionych - Policja

 Nie odnotowano

 Słowenia Ewidencja pojazdów skradzionych - Policja ✓ Nie odnotowano	 Holandia Ewidencja pojazdów skradzionych - Repozytoria Crimimail oraz Stowarzyszenie Ubezpieczycieli ✓ Nie odnotowano
 Słowacja Ewidencja pojazdów skradzionych - Policja ✓ Nie odnotowano	 Szwecja Ewidencja pojazdów skradzionych - Stowarzyszenie Ubezpieczycieli ✓ Nie odnotowano
 Norwegia Ewidencja pojazdów skradzionych - Ettersokt ✓ Nie odnotowano	 Kaynine Ewidencja przedmiotów skradzionych - Kaynine(Niemcy) ✓ Nie odnotowano
 Baza int. Ewidencja pojazdów skradzionych - Niezależne źródła internetowe ✓ Nie odnotowano	

HISTORIA POJAZDU



2023

11.2023

Serwis lub kontrola pojazdu

Stan drogomierza
271 432 km

Wymiana oleju
Wymiana oleju w skrzyni biegów
Serwis układu przeniesienia napędu
Serwis silnika

Kraj **Polska**

16.10.2023

Wykonano okresowe badanie techniczne

Stan drogomierza
270 416 km

Wynik **Pozytywny**
Termin badania technicznego **2024-10-16**
Kraj **Polska**

07.2023

Serwis lub kontrola pojazdu

Stan drogomierza
261 753 km

Wymiana płynu hamulcowego
Wymiana klocków hamulcowych
Serwis układu przeniesienia napędu

Kraj **Polska**

04.2023

Odnotowano szkodę na pojeździe

Kwota **1 500 - 1 750 PLN**
Grupa części
- Układ chłodzenia i klimatyzacji

Strefa uszkodzenia
- PrzódKraj **Polska**

04.2023

Serwis lub kontrola pojazdu

Stan drogomierza
251 537 km

Aktualizacja oprogramowania
Serwis turbosprężarki

Kraj **Polska**

01.01.2023

Ubezpieczenie pojazdu

Polisa ważna do **2023-12-31**

Kraj **Polska**

2022

08.2022

Serwis lub kontrola pojazdu

Stan drogomierza
222 392 km

Serwis układu chłodzenia silnika
Serwis układu przeniesienia napędu
Serwis silnika
Serwis turbosprężarki

Kraj **Polska**

06.2022

Serwis lub kontrola pojazdu

Stan drogomierza
216 917 km

Aktualizacja oprogramowania
Serwis układu przeniesienia napędu
Serwis turbosprężarki

Kraj **Polska**

02.2022

Serwis lub kontrola pojazdu

Stan drogomierza
211 812 kmKraj **Polska**

01.01.2022

Ubezpieczenie pojazdu

Polisa ważna do **2022-12-31**Kraj **Polska**

2021

02.10.2021

Wykonano okresowe badanie techniczne

Stan drogomierza
194 671 km

Wynik **Pozytywny**
Termin badania technicznego **2023-10-02**

Kraj **Polska**

07.2021

Zgłoszono odczyt drogomierza

Stan drogomierza
170 932 km

07.2021

Odnotowano szkodę na pojeździe

Kwota **1 000 - 1 250 PLN**

Rezultat



USZKODZENIE NADWOZIA



Strefa uszkodzenia
- Lewa strona

Kraj **Polska**

01.01.2021

Ubezpieczenie pojazdu

Polisa ważna do **2021-12-31**

Kraj **Polska**

2020

08.2020

Serwis lub kontrola pojazdu

Wymiana filtra kabinowego

Wymiana filtra oleju

Serwis instalacji gazowej

Kraj **Polska**

Stan drogomierza
120 733 km

16.07.2020

Przeprowadzenie kontroli drogowej pojazdu

Kraj **Polska**

Stan drogomierza
115 600 km

10.07.2020

Przeprowadzenie kontroli drogowej pojazdu

Kraj **Polska**

Stan drogomierza
114 598 km

05.2020

Serwis lub kontrola pojazdu

Wymiana oleju w skrzyni biegów

Serwis układu przeniesienia napędu

Kraj **Polska**

Stan drogomierza
104 829 km

01.2020

Serwis lub kontrola pojazdu

Wymiana filtra kabinowego

Wymiana filtra paliwa

Wymiana płynu chłodzącego

Stan drogomierza
82 600 km

01.01.2020

Wymiana filtra oleju

Kraj **Polska**

Ubezpieczenie pojazdu

Polisa ważna do **2020-12-31**

Kraj **Polska**

2019

10.2019

Serwis lub kontrola pojazdu

Stan drogomierza
67 040 km

Wymiana klocków hamulcowych

Wymiana tarcz hamulcowych

Kraj **Polska**

09.2019

Odnotowano szkodę na pojeździe

Kwota **1 250 - 1 500 PLN**

Grupa części

- Oświetlenie zewnętrzne



Strefa uszkodzenia
- Lewa strona

Kraj **Polska**

09.2019

Serwis lub kontrola pojazdu

Stan drogomierza
59 898 km

Serwis oświetlenia

Kraj **Polska**

06.2019

Serwis lub kontrola pojazdu

Stan drogomierza
39 776 km

Serwis regularny

Wymiana filtra kabinowego

Wymiana płynu chłodzącego

Wymiana filtra oleju

Wymiana klocków hamulcowych

Serwis oświetlenia

Serwis układu hamulcowego

Serwis instalacji gazowej

Kraj **Polska**

02.2019

Serwis lub kontrola pojazdu

Stan drogomierza
17 917 km

Kraj **Polska**

08.01.2019

Rozpoczęcie okresu gwarancyjnego

2018

05.10.2018

Wykonano dodatkowe badanie techniczne

Stan drogomierza
8 km

Badanie w celu identyfikacji lub ustalenia danych

Wynik **Pozytywny**

Kraj **Polska**

04.10.2018

Pojazd zarejestrowany

Homologowany fabrycznie

Uniwersalny

Termin badania technicznego **2021-10-03**

Kraj **Polska**

04.10.2018

Pierwsza rejestracja pojazdu

10.2018

Serwis lub kontrola pojazdu

Stan drogomierza
1 km

Przygotowanie pojazdu do wydania

Wymiana płynu chłodzącego

Uzupełnienie płynu do spryskiwaczy

Kraj **Polska**

09.2018

Pojazd wyprodukowany

Lokalizacja **Batilly**

Kolor nadwozia **Żółty**

Kierownica z lewej strony

Brak haka holowniczego

Koło zapasowe dojazdowe

Kraj **Francja**

DZIENNIK SPRAWDZEŃ

Data i czas	Rodzaj usługi	IP	Lokalizacja
--	--	--	--

WYPOSAŻENIE

PASSENGER COMPARTMENT THERMAL REQUIREMENT: PASSENGER COMPARTMENT THERMAL REQUIREMENT 1	SPECIAL EDITIONS/ADDITIONAL EQUIPMENT: WITHOUT SPECIAL EDITION ADDITIONAL DEFINITION	TYPE OF FRONT WINDOW WINDER.: DRIVER: ANTI-PINCHING PULSED / PASSENGER: MOTOR UNIT
FRONT PASSENGER SEAT ADJUSTMENT: MULTI-FUNCTION PASSENGER BENCH SEAT TYPE 4	COUNTRY OF APPLICATION OF TECHNICAL LEGISLATION: TECHNICAL REG: POLAND	WIPER START-UP TYPE: WITHOUT AUTOMATIC LIGHTS + WINDSCREEN WIPER
TECHNICAL ENVELOPES (SEE OVAL PLATE): ENVIRONNEMENTAL CONSTRAIN	TRANSPORT OR PARTNER VEHICLE TYPE: WITHOUT VEHICLE ADAPTATIO	LIMITED EDITION ADDITIONAL DEFIN: WITHOUT DEFINITION SUPPLE
DOOR OPENING REMOTE CONTROL TYPE: 315 MHZ NORMAL DOOR OPENI	SUPPLEMENTARY CONVERSION: WITHOUT SUPPLEMENTARY CONVERSION	TELEMATIC SYST FOR CUSTOMER INCI: W/O TELEMATIC SYSTEM INC
FRONT DOOR STORAGE COMPARTMENTS: WITHOUT FRONT DOOR STOR.	TYPE OF UTILITY VEHICLE REAR DOORS: WITHOUT REAR SUNROOF	COMMERCIAL VERSION SUPPLEMENT5: WO COMMERCIAL VERSION 1
COMMERCIAL VERSION SUPPLEMENT: BASIC COMMERCIAL VERSION	FRONT AND REAR PROXIMITY RADAR: WITHOUT PROXIMITY RADAR	ELECTRIC VEHICLE BATTERY CHARGING: COMPLEMENTARY OBJECT
DAYTIME RUNNING LIGHTS: WITHOUT DAYTIME RUNNING LIGHTS	COMMERCIAL VERSION SUPPLEMENT 5: WO COMMERCIAL VERSION	COMMERCIAL VERSION SUPPLEMENT2: WO COMMERCIAL VERSION
ADDITIONAL ENGINE ENVIRONMENT: WITHOUT FILTER DECANter	COMMERCIAL VERSION SUPPLEMENT3: WO COMMERCIAL VERSION	COMMERCIAL VERSION SUPPLEMENT4: WO COMMERCIAL VERSION
NAVIGATION/SMARTPHONE IMITATION: COMPLEMENTARY OBJECT	EMISSION REDUCTION SERVICE: EMISSION REDUCTION SERV 2	ON-BOARD WARRANTY/SERVICES: WO ON BOARD DOCUMENTATION
PLANT MARKING FOR COMPLEX START: COMPLEMENTARY OBJECT	HEADLIGHT BEAM ADJUSTMENT: MANUALADJUSTMENT OF HEADL	EMISSION CONTROL STANDARD: EMIS CONT EURO6B OBD IUPR
IN USE PERFORMANCE RATING: WITH IN USE PERFORMANCE R	PASSENGER COMPARTMENT HEATING TYPE: AIR-CONDITIONING	SPECIAL BUILD (FACTORY):. SERIES VEHICLE (WITHOUT S
ENGINE POWER CUT DOWN CONTROL: COMPLEMENTARY OBJECT	SHELF OF PANEL INSTRUMENT: WITH SHELF PANEL INSTRUM	SPECIAL TECHNICAL FEATURES CODE.: CONTEXT CRITERIOM
UTILITY ADAPTATION INTEG. PARTI*: CONTEXT CRITERIOM	INTERIOR CARGO SIDE TRIM: WITHOUT INTERIOR SIDE LIN	GEARBOX TYPE/NUMBER OF GEARS: 6-GEAR MANUAL GEARBOX
ADDITIONAL HEADLIGHTS: WITHOUT ADDITIONAL HEADLIGHT	SUPPLEMENTARY CHILD PACK: WITHOUT CHILD PACK SUPPLE	POWER TAKEOFF ON ENGINE: WITHOUT POWER-TAKE OFF ON
EXTERIOR ACCESSORIES COLOUR: COMPLEMENTARY OBJECT	EMERGENCY CALL AND BREAKDOWN: COMPLEMENTARY OBJECT	MISCELLANEOUS BENEFITS : MASSES: CONTEXT CRITERIOM
STORAGE FOR ACCESSORIES: WITHOUT STORAGE FOR ACCES	INVARIANT PROCESS SHEET MODEL: MODEL ROUTING SHEET	TYRE PRESSURE DETECTION: WITHOUT TYRE PRESSURE DET
EXTERIOR REAR VIEW MIRRORS: 2 ELEC OUTSIDE MIRRORS	MISCELLANEOUS BENEFITS SIXT: COMPLEMENTARY OBJECT	BIG TRUNK OPENING TYPE: WITHOUT OPENING SYSTEM FO
FRONT SEAT SUITABLE FOR CHILDREN: NON-ISOFIX SEAT	VARIOUS ADDITIONAL FEATURES: COMPLEMENTARY OBJECT	UPPER DASHBOARD STORAGE: DASHBOARD STORAGE TYPE 1

TRANSMISSION TYPE: FRONT WHEEL DRIVE TRANSMISSION	POWER TAKE-OFF ON GEARBOX: WITHOUT POWER TAKE-OFF	VEHICLE LIGHT CONVERSION: WO LIGHT ADAPTATION SVO
MISCELLANEOUS BENEFITS SEPT: COMPLEMENTARY OBJECT	REAR CONNECTION DEVICE: WO ADAPTATION CONNECTION	ELECTROMOTOR DOOR LOCKING: ELECTRIC DOOR LOCKING
EXT MIRROR PROJECTION: EXTERIOR REAR VIEW MIRROR	MISCELLANEOUS BENEFITS TER: COMPLEMENTARY OBJECT	FORWARD EMERGENCY BRAKING: COMPLEMENTARY OBJECT
RADIATOR GRILLE TINT: NON-BODY COLOURED RADIATO	MOTOR ENERGY EQUIPMENT: WITHOUT FUEL ADAPTATION	EXTERIOR DESIGNATION: WITHOUT EXTERIOR DESIGNAT
LEVEL OF NAVIGATION AID: WITHOUT NAVIGATION AID	SMOKER'S ACCESSORIES: WITHOUT SMOKER ACCESSORIE	UNDERBODY PROTECTION: WITHOUT UNDERBODY PROTECT
WIDE ANGLE REAR VIEW: WITH BUS REAR VIEW MIR 2	UTILITY ADAPTATION COVER: COMPLEMENTARY OBJECT	REAR DIFFERENTIAL LOCK: WITHOUT REAR DIFF LOCK
PARKING BRAKE TYPE: WITHOUT AUTOMATIC PARKING	WINDOWS PROTECTION: WITHOUT WINDOW PROTECTION	DRIVING ASSISTANCE: DRIVING ASSISTANCE : VEHI
REAR TOWING DEVICE: WITHOUT REAR TOWING DEVICE	REAR EXTENDED WIRING: WIRING LENGTHENS TYPE 1	DOCUMENTATION PERIOD: DOCUMENTARY PERIOD 2014
ANTI-THEFT DEVICES: WITHOUT ANTI-THEFT DEVICE	VEHICULE TRANSFORMATION: COMPLEMENTARY OBJECT	TYPE OF REFRIGERANT GAS: COMPLEMENTARY OBJECT
FIRE EXTINGUISHER: WITHOUT EQUIPMENT LEVEL O	BATTERY ISOLATION: WITHOUT BATTERY ISOLATION	INTERIOR COLOUR STYLING: INTERIOR HARMONY 01
UTILITY ADAPTATION COVER: WITHOUT ADAPTATION	TYPE OF PARTITION: COMPLETE BULKHEAD WITH WI	ENGINE HEATING ELEMENT: COMPLEMENTARY OBJECT
DRIVER'S HANDBOOK: POLISH GLOVE BOX LITERATU	TRACTION BATTERY CONTRACT: CONTEXT CRITERIOM	UNIVERSAL INTERCONNECT FUNCTION: WITHOUT TCU
ANTI-SMELL FILTER: WITHOUT ANTI-SMELL FILTER	VEHICLE TRACKING SYSTEM: W/O SECURITY DEVICE	DOOR WAIST MOLDING: WITHOUT DOOR WAIST MOLD.
BATTERY LEVEL TRACTION: COMPLEMENTARY OBJECT	BATTERY POWER TRACTION: COMPLEMENTARY OBJECT	FRONT SIDE AIRBAG: WITHOUT FRONT SIDE AIRBAG
IDLE SPEED CONTROL: WITHOUT FAST IDLE SPEED	LIGHT PROTECTION: WO PRO WIRE NETTING LIGH	INTERIOR ROOF TRIM: WITHOUT ROOF TRIM STYLE
PARTITION INSULATION: PARTITION TRIM TYPE 1	RIGHT-HAND SIDE SECTION: NO RIGHT SIDE DOOR	GEARBOX TYPE: 6-SPEED MANUAL GEARBOX - BVM6
DRIVER SEAT TYPE: DRIVER SEAT WITH LUMBAR A	WIRING FOR CONVERSION: WITHOUT WIRING ADAP.	TETE DE TRACTION: WITHOUT TETE DE TRACTION
DOCUMENTATION PHASE: DOCUMENTATION PHASE 1	ACCESSORY SOCKET: WITHOUT ACCESSORY SOCKET	UNDERBODY PROTECTION: COMPLEMENTARY OBJECT
BLIND SPOT DETECTION: COMPLEMENTARY OBJECT	ELECTRONIC STABILITY PROGRAM: PATH CONTROL	COLOR OF BUMPERS: NON-BODY COLOURED BUMPER
TRACTION BATTERY SUFFIX: CONTEXT CRITERION	LEFT-HAND SIDE SECTION: NO LEFT SIDE DOOR	WATER PROTECTION: WO RAIN FORD RIVER KIT
ENGINE CAPACITY: 2300 CM3 ENGINE CAPACITY	TYPE OF DUMPER / TRAY: WITHOUT DUMP BODY	LOAD ANCHORING POINTS: NO ANCHORING POINT
SEAT BELT REMINDER: COMPLEMENTARY OBJECT	BODY REINFORCEMENT: COMPLEMENTARY OBJECT	SERVICE COUNTRY: WITHOUT SERVICE COUNTRY
LUGGAGE COVER: WITHOUT LUGGAGE COMPARTME	ADDITIONAL FLOOR: WITHOUT FLOOR ADDITIVE	GLASSES STORAGE: WITHOUT GLASSES STORAGE
SIDE DOOR OPENING: COMPLEMENT OBJECT 053	SEATS: 3RD ROW: 0 SEAT - THIRD ROW SEATS	TRACTION BATTERY TYPE: CONTEXT CRITERION
MAKE OF TYRES: TYRE BRAND: UNMARKED FITT	GEOGRAPHIC COUNTRY: COMPLEMENTARY OBJECT	UTILITY VEHICLE WHEELBASE: WHEELBASE 30
VARIOUS FUNCTIONS: COMPLEMENTARY OBJECT	SEAT HEATER AND COOLER: NON-HEATED SEAT	ADAPTATION ELECTRIC: ADAPTATION FLASHER

REAR STEP BOARD: WITHOUT REAR SIDE SILL	TYPE OF BATTERY: NON-REINFORCED BATTERY	APPROVAL TYPE: APPROVAL TYPE N1 CLASS 3
SELECTIVE CATALYTIC REDUCTION: WITH SCR	PRESTATION EIGHT: COMPLEMENTARY OBJECT	REAR CARPET - FLOOR: CONTEXT CRITERIOM
ADDITIONAL KEY: WITHOUT ADDITIONAL KEY	PLUG OPENING INLETS: WITHOUT DUST-CAP	CRUISE CONTROL: WITHOUT CRUISE CONTROL
STOP AND START: WITHOUT STOP AND START	POLLEN/DUST FILTER: WITH POLLEN FILTER	STARTUP CRITERIA: COMPLEMENTARY OBJECT
INSTRUMENT PANELS: INSTRUMENT PANEL 09	LEVEL OF MOTORIZATION: MY ENGINE LEVEL	PARTICLE FILTER: WITH PARTICLE FILTER
SPECIAL CONVERSION: CONTEXT CRITERIOM	SIDE STEP BOARD: WITHOUT SIDE S.BOARD	MARKETING VERSION: COMMERCIAL VERSION
SPEED LIMITER.: WITHOUT SPEED LIMITER	WHEEL RIM TYPE: 16 METAL WHEEL RIMS 1	DETECTOR SAFETY: COMPLEMENTARY OBJECT
SEAT COVERS: FABRIC SEAT-LINING N 01	PLANT ASSEMBLY LINE: ASSEMBLY LINE 1	REAR WINDOW: NON-HEATED REAR SCREEN
EQUIPMENT LEVEL: EQUIPMENT LEVEL E2	LUGGAGE RACK: WITHOUT UPPER STORAGE	DOOR SECURITY: DOOR.LOCK.BY RUNNING
FRONT ROOF STORAGE: NO ROOF STORAGE	LANE KEEP: W/O LANE DEPARTURE WARNI	FUEL TANK CAPACITY: 80 LITRES TANK
TYPE OF CLIMATE: TEMPERATE CLIMATE	POWER IN DIN HP / KW: 096 KW POWER	WHEELS ANTI-SKID: WHEELS ANTI-SKID
MUD FLAP: MUD-GUARDS WITHOUT FLAPS	INCREASED PAYLOAD: NORMAL PAY LOAD	MODE 2 CABLE: COMPLEMENTARY OBJECT
DOUBLE TIRE: WITHOUT WHEEL COUPLED	FRONT ARM REST: WITH FRONT ARMREST	SEAT REMOVABLE: SEAT NOT REMOVABLE
ADDITIONAL LOCK: CONTEXT CRITERIOM	ENGINE TYPE: 2.3 DCI DIESEL ENGINE	SERVICE TMC: COMPLEMENTARY OBJECT
REAR BODY SIDE: WITHOUT BODY SIDE	USE OF ALTERNATOR: ALTERNATOR 70A	DUST PROTECTION: WITHOUT DUST KIT
CONDITIONING: STANDARD PROTECTION	CAPACITY: GROSS VEH WEIGHT 3500KG	WHEELS RIMS: COMPLEMENTARY OBJECT
SERVICE AHA: COMPLEMENTARY OBJECT	TYPE OF HEADLIGHTS: HEADLIGHT 01	NAVIGATION MAP: STANDARD MAPPING
MODEL YEAR: COMPLEMENTARY OBJECT	ROAD SEVERITY: NORMAL SUSPENSION	REAR SCREEN BLIND: WITHOUT BLIND
FRONT SPOILER: WITHOUT DEFLECTOR	SPARE WHEEL: WITH A SPARE WHEEL	ECONOMIC DRIVING: WITH ECO MODE
STRIPPING: COMPLEMENTARY OBJECT	REAR OVERHANG: NORMAL OVERHANG	REAR BOX: WITHOUT LUGGAGE RACK
PROTECTION ELEMENTS: DR AIRBAG	ROUTING SHEETS COUNTRY: POLAND	TYPE OF FUEL OR ENERGY: DIESEL
TACHOGRAPH: WITHOUT TACHOGRAPH	STEERING WHEEL POSITION: LEFT	REAR GATE: WITHOUT SIDE BOARD
BODY COLOUR: YELLOW LEMON BC	WHEELBASE LENGTH: LENGHT L3C	LUGGAGE BOX: W/O LUGGAGE BOX
TYPE OF TIRES: STANDARD TYRE	ROOF HUE: BODY COLOURED ROOF	TOW HOOK.: WITHOUT ROOF RACK
ROOF RACK/BARS: NO ROOF RACK	LAYOUT: COMPLEMENTARY OBJECT	ROOF HEIGHT: HEIGHT ROOF 10
LADDER: WITHOUT DOOR LADDER	WINDOW TINT: WITHOUT GLASS	BODYWORK TYPE: CAB CHASSIS
TYPES OF RADIOS: RADIO 33A	TRACK WIDTH: STANDARD AXLE	BRAND DESIGNATION: RENAULT
ENGINE SUFFIX: 704 INDEX	COUNTER UNIT: KILOMETRES	SEAT TRIMS: VELVET CLOTH

HORN: CONTEXT CRITERIOM

2ND ROW SEATS: WITHOUT

WHEEL TRIM: HUBCAP 01

ARCHIWALNE ZDJĘCIA POJAZDU

Liczba zdjęć --

Zasady i warunki

Wszelkie informacje udostępnione za pośrednictwem serwisu autoDNA mają charakter informacji pomocniczych i stanowią jedynie wskazówki dla Użytkownika.

Informacje zawarte w serwisie autoDNA mogą ulec zmianie, bez wcześniejszego powiadomienia przez AUTODNA Sp. z o.o. o tym fakcie. Wszelkie treści i znaki graficzne zamieszczone w serwisie autoDNA chronione są prawami autorskimi przysługującymi AUTODNA Sp. z o.o. Wykorzystywanie tych treści lub znaków graficznych w sposób inny niż wyraźnie dozwolony warunkami Regulaminu serwisu autoDNA, stanowi jego naruszenie i złamanie obowiązujących przepisów prawa, w szczególności przepisów ustawy z dnia 4 lutego 1994 r. o prawie autorskim i prawach pokrewnych (tekst jednolity: Dz. U. 2006 r. Nr 90 poz. 631).

Użytkownik może pobierać pojedyncze kopie materiałów publikowanych w serwisie autoDNA wyłącznie do użytku własnego.

Zabronione jest powielanie, kopiowanie, przesyłanie, przechowywanie w systemach, dokonywanie tłumaczenia na inny język lub inne, sprzeczne z Regulaminem serwisu autoDNA, wykorzystywanie treści udostępnianych za pośrednictwem serwisu autoDNA, bez uprzedniej, wyraźnej, pisemnej zgody AUTODNA Sp. z o.o.

AUTODNA Sp. z o.o. może posiadać patenty, zgłoszenia patentowe, prawa autorskie, znaki towarowe oraz inne prawa własności intelektualnej dotyczące treści udostępnianych za pomocą serwisu autoDNA w jakiegokolwiek formie.

AUTODNA Sp. z o.o. udostępniając treści za pośrednictwem serwisu autoDNA nie udziela licencji na patenty, prawa autorskie, znaki towarowe lub inne prawa własności intelektualnej, zawarte w udostępnionych treściach.

Nazwy podmiotów lub produktów zawarte w treściach, udostępnianych przez AUTODNA Sp. z o.o. w jakiegokolwiek formie za pośrednictwem serwisu autoDNA, mogą stanowić zarejestrowane znaki towarowe lub znaki usługowe tych podmiotów.

autoDNA

**Raport Historii Pojazdu
autoDNA**



VF1VB000260697789
Renault Master



Jak skanować QR kod

Uruchom aparat w swoim telefonie i skieruj obiektyw telefonu na kod QR. Telefon automatycznie zeskanuje QR kod. Alternatywnie, uruchom aplikację do skanowania QR i postępuj analogicznie.



Jak nakleić na szybę

Naklej na boczną szybę samochodu, po prawej lub lewej stronie. Nie rekomendujemy naklejania na przednią szybę, która ustawiona jest pod kątem przez co trudniej będzie zeskanować QR kod.



Jak umieścić zdjęcie w ogłoszeniu

Dodaj QR kod jako kolejne zdjęcie do swojego ogłoszenia. Popularne serwisy umożliwiają dodawanie zdjęcia w rozmiarze do 5 MB o rozdzielczości 1080 x 720 px. Plik, który otrzymałeś od nas wraz z zamówionym raportem spełnia te wymagania. Po prostu dodaj zdjęcie do galerii sprzedawanego pojazdu.